

Weekly Construction Report Hatchery Creek Design/Build Project



Time Period:	December 1	14-20, 2014	Project No:	1305
Rain Days/Weather Conditions:		No Rain this wee	k	
Personnel on-site:		EcoGro/Ridgewater: Tony Berry, Tom Cutter, Eric Dawalt, Brad Redmon, & Chad Relinski. Stantec: N/A		
Equipment on-site:		Komatsu PC 160 w/ hyd. thumb, PC 360 w/ hyd. thumb, Terex TA27 articulating dump truck, Bobcat T300 skid steer, & Morooka 2200 VD Tracked Dump Truck (demobilized on 12/19).		
Material deliveries to project site:		■ N/A		
Work performed the past week:		 Installed overflow channel (notch) at Trib. Z at RT Sta. 159+00 to elevation 572', and stabilized with rock on the downstream face. Finished site stabilization and cleaned-up site for winter. Helped Aspen haul dirt from Site #3 to ponds in the disposal area. Installed rock check dam upstream of "Lunker Bunker" pool at Sta. 147+00. 		
Erosion & sediment controls installed/maintained:		 Installed sediment traps and rock check dams along top of ravine, rock spillway, temporary diversion and ravine/channel confluence bar area. Installed seed and straw on all disturbed areas along ravine, rock spillway, and temporary diversion. Constructed plunge pool in ravine, and pool in channel downstream of bridge are serving as sediment basins. 		
Work scheduled for next week:			Ridgewater will be breaking fro 4th for Christmas.	
Work planned for two weeks ahead:		Cut down large Sycamore tree on river bank/top of channel slope at ~ LT Sta. 159+80.		
General Comme		excavate hauled s installed from Dec	construction, the USACE excaved soil from Site #3 from Sta. 19 oil stockpile out of Site #3 to di Erosion & Sediment controls. Cember 20th to January 4th for	59+00 to 158+00 and sposal area. They also They will also be breaking
Prepared by: Brad Redmon		Date: 12-20-14		· ·



Weekly Construction Report

Hatchery Creek Design/Build Project



Pictures from the past week's construction:



Aspen Construction excavating step pool reach at tie-in to Cumberland River (Photograph taken at ~Sta. 160+00 looking upstream).



Step pool reach being excavated by Aspen Construction. Large sycamore tree in center of photograph will be removed (Photo taken at ~Sta. 159+500 on right descending bank looking across the new channel).



Weekly Construction Report Hatchery Creek Design/Build Project





Haul road to Site #3 being used by Aspen Construction truck.



Haul road to Site #3 being maintained by Aspen Construction between truck loads.



Weekly Construction Report

Hatchery Creek Design/Build Project





Seed and straw installed along ravine upstream of bridge (Photo taken at ~Baseline Sta. 302+00 on left descending bank looking downstream toward Public Fishing Area).



Silt traps, seed, and straw installed along ravine downstream of bridge (Photo taken at ~Baseline Sta. 204+50 on right descending bank looking upstream toward bridge).